

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>B 10411 - 15</b>	
7. Unit Agreement Name <b>S. Caprock Queen Unit</b>	
8. Farm or Lease Name <b>S. Caprock Queen Unit</b>	
9. Well No. <b>T-21, W-13, Sec. 20</b>	
10. Field and Pool, or Wildcat <b>S. Caprock Queen Unit</b>	
12. County <b>Chaves</b>	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name <b>S. Caprock Queen Unit</b>	
2. Name of Operator <b>Union Oil of California</b>		8. Farm or Lease Name <b>S. Caprock Queen Unit</b>	
3. Address of Operator <b>500 N. Marienfeld - Midland, Texas 79701</b>		9. Well No. <b>T-21, W-13, Sec. 20</b>	
4. Location of Well UNIT LETTER <b>M</b> , <b>660</b> FEET FROM THE <b>S</b> LINE AND <b>660</b> FEET FROM THE <b>W</b> LINE, SECTION <b>20</b> TOWNSHIP <b>15 S</b> RANGE <b>31 E</b> NMPM.		10. Field and Pool, or Wildcat <b>S. Caprock Queen Unit</b>	
15. Elevation (Show whether DF, RT, GR, etc.) <b>GL 4441</b>		12. County <b>Chaves</b>	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

### Plugging Procedures Below:

1. 12 1/4" @ 200' W/200 Sx.
2. 7" @ 3100' W/125 Sx.
3. Perf. @ Open Hole 3100' - 3136'

Plug #1 30 Sx. @ 3100'  
Plug #2 25 Sx. @ 7" Stub  
Plug #3 35 Sx. @ Base of Surface 200'  
Plug #4 5 Sx. @ Surface

Establish Dry Hole Marker

*Note: 25 Sx at top Salt  
if not behind #"*

H. D. Oden, Inc.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H. D. Oden TITLE Agent for Union Oil of California DATE August 4, 1971

APPROVED BY John W. Runyan TITLE Geologist DATE AUG 9 1971

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

AUG - 9 1971

OIL CONSERVATION COMM.  
HOBBS, N. M.