

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E 5988

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name S. Caprock Queen Unit
2. Name of Operator Union Oil of California	8. Farm or Lease Name S. Caprock Queen Unit
3. Address of Operator 500 N. Marienfeld - Midland, Texas	9. Well No. T-41, W-12, Sec. 20
4. Location of Well UNIT LETTER L , 660 FEET FROM THE W LINE AND 1980 FEET FROM THE S LINE, SECTION 20 TOWNSHIP 15 S RANGE 31 E NMPM.	10. Field and Pool, or Wildcat S. Caprock Queen Unit
15. Elevation (Show whether DF, RT, GR, etc.) GL 4416	12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging Procedures Below:

1. 8 5/8" @ 314' W/300 Sx.
2. 5 1/2" @ 3127' W/100 Sx.
3. Perf. @ Open Hole 3127' - 3137'

Plug #1 - 25 Sx. @ 3100'
Plug #2 - 5 Sx. @ Surface

Recovered 3000' Tubing

Establish Dry Hole Marker

H. D. Oden, Inc.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE H. D. Oden TITLE Agent for Union Oil of California DATE August 12, 1971

APPROVED BY Nathan E. Clegg TITLE Commissioner DATE August 12, 1971
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 4 1975

OIL CONSERVATION COMM.
WASH. D. C.

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
5. State Oil & Gas Lease No. E 5988	
7. Unit Agreement Name S. Caprock Queen	
8. Farm or Lease Name S. Caprock Queen	
9. Well No. T-41, W-12, Sec. 20	
10. Field and Pool, or Wildcat S. Caprock Queen	
12. County Chaves	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Union Oil of California
3. Address of Operator 500 N. Marienfeld - Midland, Texas
4. Location of Well UNIT LETTER B 660 FEET FROM THE W LINE AND 1980 FEET FROM THE S LINE, SECTION 20 TOWNSHIP 15 S RANGE 31 E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) GL 4416

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

PLUG AND ABANDON	<input checked="" type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>	PLUG AND ABANDONMENT	<input type="checkbox"/>
CASING TEST AND CEMENT JOB	<input type="checkbox"/>	OTHER	<input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging Procedures Below:

1. 8 5/8" @ 314' W/300 Sx.
2. 5 1/2" @ 3127' W/100 Sx.
3. Perf. @ Open Hole @ 3127' - 3128'

Plug #1 - 25 Sx. @ 3100'
Plug #2 - 25 Sx. @ 5 1/2" Stub
Plug #3 - 35 Sx. @ Base of Surface 314'
Plug #4 - 5 Sx. @ Surface

Establish Dry Hole Marker

H. D. Oden, Inc.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>H. D. Oden</u>	TITLE <u>Agent for Union Oil of California</u>	DATE <u>July 20, 1971</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>SUPERVISOR DISTRICT I</u>	DATE <u>JUL 23 1971</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

JUL 02 1971

U.S. AIR FORCE COMM.
HQS, AFM.

100-100