

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E 5819	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Union Oil of California		S. Caprock Queen
3. Address of Operator		9. Well No.
500 N. M arienfield - Midland, Texas		T-40, W-5, Sec. 20
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER E , 1980 FEET FROM THE N LINE AND 660 FEET FROM		S. Caprock Queen
THE W LINE, SECTION 20 TOWNSHIP 15 S RANGE 31 E NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
GL 4413		Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging Procedures Below:

1. 13 3/8" @ 320' Circ.
2. 5 1/2" @ 3098' W/125 Sx.
3. Perf. Open Hole @ 3098' - 3112'

Plug #1 - 25 Sx. @ 3100'
Plug #2 - 25 Sx. @ 5 1/2" Stub
Plug #3 - 35 Sx. @ Base of Surface 320'
Plug #4 - 5 Sx. @ Surface

Establish Dry Hole Marker

H. D. Oden, Inc.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H. D. Oden TITLE Agent for Union Oil of California DATE July 20, 1971

APPROVED BY [Signature] TITLE SUPERVISOR DISTRICT I DATE JUL 23 1971

CONDITIONS OF APPROVAL, IF ANY: