

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator Union Oil of California	5. State Oil & Gas Lease No. 16 064000
3. Address of Operator 500 N. Maricopa - Midland, Texas	7. Unit Agreement Name S. Caprock Queen Unit
4. Location of Well UNIT LETTER C , 1980 FEET FROM THE 4E LINE AND 1980 FEET FROM THE N LINE, SECTION 30 TOWNSHIP 13 N RANGE 31 E NMPM.	8. Farm or Lease Name S. Caprock Queen Unit
	9. Well No. 7-43, V-7, Sec. 30
	10. Field and Pool, or Wildcat S. Caprock Queen Unit
15. Elevation (Show whether DF, RT, GR, etc.) CL. 4492	12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging Procedures Follow:

1. 8 5/8" @ 300'
2. 5 1/2" @ 3200' w/150 Sz.
3. Perf. @ 3115' - 3120'

Plug #1 - 100' Plug @ Perf.
Plug #2 - 100' Plug @ Start of 5 1/2"
Plug #3 - 100' Plug in and out of surface
Plug #4 - 20' Plug @ Surface

Establish Dry Hole Marker

H. D. Olsen, Inc.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H. D. Olsen	TITLE Agent for Union Oil of California	DATE June 30, 1971
APPROVED BY [Signature]	TITLE SUPERVISOR DISTRICT I	DATE JUL 7 1971
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

JUL 6 1971

OIL CONSERVATION COMM.
HOBBS, N. M.