

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
LC 064900

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	S. C prock Queen Unit
3. Address of Operator	8. Farm or Lease Name
Union Oil of California	S. C prock Queen Unit
9. Well No.	
3. Address of Operator	7-39, W-2, Sec. 30
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER E , 660 FEET FROM THE N LINE AND 1900 FEET FROM	S. C prock Queen Unit
THE E LINE, SECTION 30 TOWNSHIP 25 S RANGE 31 E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
OL 4451	Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging Procedures Below:

1. 8 5/8" @ 301'
2. 5 1/2" @ 3128' w/400 Gr.
3. Perf. @ 3118' - 3130'

Plug #1 - 100' Plug @ Perf.
Plug #2 - 100' Plug @ Start of 5 1/2"
Plug #3 - 100' Plug in and out of Surface
Plug #4 - 20' Plug @ Surface

Establish Dry Hole Marker

H. D. Oden, Inc.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H. D. Oden TITLE Agent for Union Oil of California DATE June 30, 1971

APPROVED BY [Signature] SUPERVISOR DISTRICT 1 DATE JUL 7 1971

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUL 10 1971

**OIL CONSERVATION COMM.
HOBBS, N. M.**