

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

HUBBS OFFICE D.C.C.

APR 28 11 03 AM '69

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator American Petrofina Company of Texas		8. Farm or Lease Name North Caprock Queen Unit #1
3. Address of Operator Box 1311, Big Spring, Texas 79720		9. Well No. 15
4. Location of Well UNIT LETTER 0 660 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 36 TOWNSHIP 12S RANGE 31E NMPM.		10. Field and Pool, or Wildcat North Caprock Queen
15. Elevation (Show whether DF, RT, GR, etc.) 4395 GR		12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Start work approximately 6-11-69

1. Spot 50 sk cement plug at TD 3055' through 2" EUE tubing using mud laden fluid as displacing medium. Bottom of 6-1/2" casing is at 2990'.
2. Cut off 5-1/2" casing at 660' and pull.
3. Run 2" EUE tubing to 660' (or 5-1/2" casing stub) and spot 25 sk cement plug.
4. Spot 25 sk cement plug at 303' (Bottom of 8-5/8" casing).
5. Place 10 sk cement plug in top of 8-5/8" casing and set 4" pipe marker.

10

JCC/js

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. M. Denson

TITLE Asst. Dist. Mgr. of Production DATE April 28, 1969

APPROVED BY [Signature]

TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: