

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.G.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

|  |
|--|
| 5a. Indicate Type of Lease   |
| State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No.   |
| <b>B-8605</b>  |

|  |                                   |
|--|-----------------------------------|
| <p align="center"><b>SUNDRY NOTICES AND REPORTS ON WELLS</b><br/>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)</p> |                                   |
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Water Injection</b>   | 7. Unit Agreement Name            |
| 2. Name of Operator  | <b>North Caprock Queen Unit 2</b> |
| 3. Address of Operator   | 8. Farm or Lease Name             |
| <b>Blue Supply Co., Inc. Anadarko Production Co.</b>   | <b>Tract #11</b>                  |
| 4. Location of Well  | 9. Well No.                       |
| <b>P.O. Box 647 Artesia, New Mexico 88210</b>  | <b>#1</b>                         |
| UNIT LETTER <b>N</b> <b>660</b> FEET FROM THE <b>South</b> LINE AND <b>1980</b> FEET FROM  | 10. Field and Pool, or Wildcat    |
| THE <b>West</b> LINE, SECTION <b>1</b> TOWNSHIP <b>13-S</b> RANGE <b>31-E</b> NMPM.  | <b>Caprock Queen</b>              |
| 15. Elevation (Show whether DF, RT, GR, etc.)  | 12. County                        |
| <b>4407 GL</b>   | <b>Chaves</b>                     |

|  |   |
|--|---|
| 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data |   |
| NOTICE OF INTENTION TO:  | SUBSEQUENT REPORT OF:                               |
| PERFORM REMEDIAL WORK <input type="checkbox"/>                               | REMEDIAL WORK <input type="checkbox"/>              |
| TEMPORARILY ABANDON <input type="checkbox"/>                                 | COMMENCE DRILLING OPNS. <input type="checkbox"/>    |
| PULL OR ALTER CASING <input type="checkbox"/>                                | CASING TEST AND CEMENT JOB <input type="checkbox"/> |
| OTHER <input type="checkbox"/>   | OTHER <input type="checkbox"/>                      |
| PLUG AND ABANDON <input checked="" type="checkbox"/>                         | ALTERING CASING <input type="checkbox"/>            |
| CHANGE PLANS <input type="checkbox"/>  | PLUG AND ABANDONMENT <input type="checkbox"/>       |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**Intend to plug and abandon well as follows:**

1. Pull tubing and packer.
2. Set cast iron bridge plug at base of 4 1/2" liner approximately 3015'.
3. Spot 25 foot cement plug on top of bridge plug.
4. Knock off oil string at free point, approximately 1200'.
5. Set 25 sack cement plug at casing out off point.
6. Set 10 sack cement plug at surface.
7. Set surface marker.
8. Remove all equipment and clean up location.

*25 5x5 in & out of surface csg. shoe  
Heavy mud between all plugs*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

|                                 |                                    |                        |
|---------------------------------|------------------------------------|------------------------|
| SIGNED <i>[Signature]</i>       | TITLE <b>Secretary agent</b>       | DATE <b>10-28-71</b>   |
| APPROVED BY <i>[Signature]</i>  | TITLE <b>SUPERVISOR DISTRICT I</b> | DATE <b>NOV 8 1971</b> |
| CONDITIONS OF APPROVAL, IF ANY: |                                    |                        |

RECEIVED

MAY 4 1971

OIL CONSERVATION COMM.  
WASH., D.C.