(Feb. 1961)				

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office		
Lease No	_MM_	015868
Unit	P	
*: 4		•

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	X	SUBSEQUENT REPORT OF WATER SHUT-OFF
		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
	i	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	- -	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL		
(INDICATE ABOVE BY CHECK M	IARK NAT	URE OF REPORT, NOTICE, OR OTHER DATA)

		06	ober 16	, 19
Willians Federal Well No. 2 is locate	d 990 ft. 1	from_ $ {N \choose S}$ line	$n \begin{Bmatrix} E \\ W \end{Bmatrix}$ line of sec. 10	
97 A. Saakkan 10	138	31.E	NOUPM	, .
SE/4 Section 10	(Twp.)	(Range)	(Meridian)	•
Undesignated	C)ba	TOS	N dw M	exci.00
(Field)	(Co	unty or Subdivision)	(8	State or Territory)
Corpus	79		4	

The elevation of the derrick floor above sea level is 4425.3ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Propose to set 8.5/8" 2½# surface casing at 300 feet and circulate cement to surface. Drill 7.7/8" hole to top of Queen sand at 3000 feet and core. Set 5.1/2" 1½# oil string at top of Queen sand and cement back to above base of salt.

l understand	that this plan of work must receive approval in writing	by the Geological Survey before operations may be commenced.
Company	John L. Harlan	
Address	Box 355	
	Monahans, Texas	By Cananach
		Title Petroleum Engineer

FORM C=128 Revised 5.11 57

NEW MEXICO OIL CONSERVATION COMMISSION

TION DIAT

	(FF IN	STRUCTIONS FOR CO	MPLET	ING THIS FOI	RM ON THE F	REVERSE SIDE	and the state of t
	322			TION A			The second se
Operator			Les				Well No.
	ohn L. Hari	an.		W	illiams	Federal	2
Unit Letter P	Section 10	Township 13 South		Range 31 Bast	Coho		haves
-	Location of Vell.	13 30utn		JI Dast	<u></u>		пачев
990	feet from the	South line at	a.d	330	feet from th	East	lipe
Ground Level El			Pod			2006	ledicated Acreage:
4425.3	1					1	Acces
		the dedicated acreage					Tuner means the person
ubo bas the	right to drill into an	d to produce from any p	ool and	l to appropriate	the product.	en pys. – Ainna	se for the himself and
	5-3-29 (e) NMSA 15						
							estion agreement of other-
		If answer is "yes," Ty					nagangangan at an ang ang mga mga mga mga mga mga mga mga mga mg
	r to question two is	"no," list all the owne	re and			erity w seed of the seed of the	
Owner				Land De	#Cription		
							The control of the co
						e e e e e e e e e e e e e e e e e e e	The state of the s
		SECTION B					CERTIFICATION
						e capera	
•		İ		į			couly that the information
				1		1 1	25 A above is true and com- e best of my knowledge and
	i			1		The state of the s	e sest of my knowledge and
	İ			` !			
				ļ			1,4
		4		;			HAMAMAN
						Lastion	
	1			!		e de la companya del companya de la companya del companya de la co	and the second s
	1			: -		Compacy	
						i jirin	SECURE OF THE PROPERTY OF THE
Í				I			
	ļ			Ì		de formación manager en estado de la composición dela composición de la composición de la composición dela composición dela composición dela composición de la composición dela composición de la composición de la composición dela composic	
1	i			1			
					The state of the s		
1	1					্ত তেওকাইফ	entity that the well location
	1	!				Society on	the plac to SECTION B was
1		¥ 9 9				i parted fro	m field notes of actual
1	i i			į		្ មួយស្រីស្សាសា ព	ade by me or under my
				1			on, and that the same is true
	1						it to the beat of my knowledge
						and tellet	
	.			1	- > ₀%	30 ¹	
1	 	1		•	1	Date Surv	
.	ł , 1				0	1	10-10-61
	1			1	066		d Professional Engineer
	İ				1	and/or La	ad Surveyor, JOHN W WEST
	1			i	¥	1	las 4/1/10 +
-						10	my w www
0 330 660	990 /320 /650	1980 2310 2640	2000	1500 100	0 500	o Suncia	P.E. & L.S. NO. 878