

COPIES RECEIVED		
DISTRIBUTION		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-8631	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Water Injection		7. Unit Agreement Name North Caprock Queen Unit 2
2. Name of Operator Anadarko Production Company		8. Farm or Lease Name Tract #27
3. Address of Operator P. O. Box 647, Artesia, New Mexico 88210		9. Well No. 7
4. Location of Well UNIT LETTER K , 1650 FEET FROM THE South LINE AND 2310 FEET FROM THE West LINE, SECTION 11 TOWNSHIP 13S RANGE 31 E NMPM.		10. Field and Pool, or Wildcat Caprock Queen
15. Elevation (Show whether DF, RT, GR, etc.) 4422 GL		12. County Chaves

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set abandonment plug at 3035. Pumped 25' cement on top of plug, cut off oil string at 965'. Pumped 25 sacks cement at casing cut off point, pumped 25 sacks cement at base of surface casing, 10 sacks at surface with heavy mud between all plugs. Set surface marker and cleaned up location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>B. D. Muncy, Jr.</u>	TITLE <u>Agent</u>	DATE <u>5/10/74</u>
APPROVED BY <u>John W. Remyan</u>	TITLE <u>Geologist</u>	DATE <u>DEC 7 1974</u>
CONDITIONS OF APPROVAL, IF ANY:		