

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-8631-3	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- Injection Well		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Great Western Drilling Company		
3. Address of Operator		9. Well No.
Box 1659, Midland, Texas		See #1, Well No. 6
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER F , 2310 FEET FROM THE North LINE AND 2310 FEET FROM		Caprock Queen
THE West LINE, SECTION 11 TOWNSHIP 13-S RANGE 31-E NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
4418 GR		Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The hole will be loaded with 10# mud. A 25 sack cement plug set at 3030'. Some 1500' of 5-1/2" casing will be pulled and 25 sacks placed in the stub. Should this casing expose the salt - 25 sacks will be placed above the salt. 25 sacks will be placed at the shoe of the surface pipe 312' and 10 sacks at the surface. A proper marker and cleanup will be made.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *O. H. Crews* **O. H. Crews** TITLE **Administrative Coordinator** DATE **April 25, 1966**

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: