NO. OF COPIES RECEIVED				Form C-103
DISTRIBUTION				Supersedes Old C-102 and C-103
SANTA FE		NEW MEXICO OIL CONSERY	VATION COMMISSION	Effective 1-1-65
FILE				
U.S.G.S.				5a. Indicate Type of Lease
LAND OFFICE				State A Fee
OPERATOR			5. State Oil & Gas Lease No.	
		•		B-10416-25
(DO NOT USE THIS FORM	SUNDE	LY NOTICES AND REPORTS ON WE OPPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK ION FOR PERMIT -" (FORM C-101) FOR SUCH PR	LLS TO A DIFFERENT RESERVOIR. ROPOSALS.)	
1.	7. Unit Agreement Name			
OIL A GAS WELL WELL	rth Caprock Queen Unit 2			
2. Name of Operator	8. Farm or Lease Name			
Anada <b>rko</b> Pro	Tract #22			
3. Address of Operator	9. Well No.			
P. O. Box 67	#1			
4. Location of Well	10. Field and Pool, or Wildcat			
0	(	560 FEET FROM THE South	1980	Caprock Queen
		on 12 Township 13-S		
	12. County			
	Chaves			
<sup>16</sup> .	heck	Appropriate Box To Indicate Natu	ure of Notice. Report or Ot	her Data
NOTICE	T REPORT OF:			
PERFORM REMEDIAL WORK		PLUG AND ABANDON	EMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		c.	OMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING		CHANGE PLANS	ASING TEST AND CEMENT JOB	
			OTHER	
		[]	<del></del>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Intend to plug and abandon well as follows:

- 1. Pull tubing and rods.
- 2. Set cast iron bridge plug at base of 52" casing approximately 2980'.
- 3. Spot 25 foot cement plug on top of bridge plug.
- 4. Set 10 sack cement plug at surface.
- 5. Set surface marker.
- 6. Remove allequipment and clean up location.

No casing will be pulled from well.

18. I hereby certify that the information above	true and complete to the best of my knowledge and belief.	
SIGNED Works SQU	District Superintendent	DATE Sept. 8, 1971
D. R. Layton	Hig. Signed by Joe D. Ramey	SEP 13 1971
APPROVED BY	Title Tist I, Supre	DATE

## RECEIVED

SEP 10 1971

OIL CONSERVATION COMM. HOBBS, N. M.