

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
E-7659

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Water Injection Well	7. Unit Agreement Name
2. Name of Operator	No. Central Caprock Queen
Great Western Drilling Company	8. Farm or Lease Name Unit 14
3. Address of Operator	9. Well No.
P. O. Box 1659 Midland, Texas 79701	9
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER I , 1980 FEET FROM THE South LINE AND 660 FEET FROM	Caprock Queen
THE East LINE, SECTION 14 TOWNSHIP 13-S RANGE 31-E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
4413 T/Tbg. Head	Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On 5-20-70 ran tubing and set a 25 sack cement plug at 3049'. Pulled 35 joints of tubing and shut well in overnight; plug held OK. Loaded hole with mud and pulled 1,210' of 4-1/2" casing. Set 25 sack cement plugs at 1,210' and 264'. Set a 10 sack cement plug and marker at surface. Plugging operations completed 5-23-70.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *R.I. Comstock* **R.I. Comstock** TITLE **Chief Engineer** DATE **June 2, 1970**

APPROVED BY *John W. Runyan* TITLE **Geologist** DATE **FEB 24 1971**

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUN 3 1970

OIL CONSERVATION COMM.
HOBBS, N. M.