

OF COPIES RECEIVED		
DISTRIBUTION		
DATE		
G.S.		
AND OFFICE		
PERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-10418-75
7. Unit Agreement Name ROCK QUEEN UNIT
8. Farm or Lease Name <del>TRACT NO. 7</del>
9. Well No. 22-14
10. Field and Pool, or Wildcat CAPROCK QUEEN
12. County CHAVES

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT - I" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER- WATER INJECTION WELL
Name of Operator GREAT WESTERN DRILLING COMPANY		
Address of Operator P. O. BOX 1659 MIDLAND TX 79701		
Location of Well UNIT LETTER N 660 FEET FROM THE SOUTH LINE AND 1980 FEET FROM THE WEST LINE, SECTION 22 TOWNSHIP 13-S RANGE 31-E NMPM.		

15. Elevation (Show whether DF, RT, GR, etc.)  
DF 4433'

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
ILL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMOCC notified 24 hrs. prior to setting bottom plug.

2-24-76 RU csg. pullers. Ran tbg & tagged bottom @ 3004'. Spotted 25 sx plug @ 3004'. Ran wireline meas. & tagged plug @ 2784' (220' plug). RU csg jacks.

2-25-76 Shot csg @ 1249'. Rec. 40 jts 5½" csg (1254.13"). Ran tbg to bottom plug. Displaced hole w/9.5#/gal. brine mud. Spotted 20 sx plug 1299'-1199'. Spotted 30 sx plug 230'-128' & 10 sx plug @ surface w/dry hole marker.

PLUGGED AND ABANDONED 2-25-76.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>F.L. Ballard</u>	TITLE <u>F.L. Ballard</u>	DATE <u>3-3-76</u>
ORIG. SIGNED BY <u>John Runyan</u>	TITLE <u>Geologist</u>	DATE <u>NOV 6 1976</u>
APPROVED BY _____	CONDITIONS OF APPROVAL, IF ANY:	