STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

	T		
DISTRIBUTION			
BANTA FE			
FILE			
U.1.G.1.			
LAND OFFICE			
OPPRATOR	7		

OIL CONSERVATION DIVISION

Form C-103

DISTRIBUTION	P. O. BOX	X 2088	Revised 10-1-78		
SANTA FE	SANTA FE, NEW	SANTA FE, NEW MEXICO 87501			
FILE	1		Sa. Indicate Type of Lease		
U.\$.G.\$.]		State XX Fee		
LAND OFFICE]		5. State Oil & Gas Lease No.		
OPERATOR]	0-005-00824	E-7659		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUC BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPESALS.)			7. Unit Agreement Name		
1. OIL GAS	ormer. Injection Well	1			
WEET WEET			8. Farm or Lease Name		
2. Name of Operator			Rock Queen Unit Sec. 23		
Circle Ridge Production, Inc.		9. Well No.			
c/o Oil Reports & Gas Services, Inc., Box 755, Hobbs, NM 88241			4		
4. Location of Well			10. Field and Pool, or Wildcat		
			Caprock Queen		
THE WEST LINE, SECTION 23 TOWNSHIP 13S BANGE 31E NMPM.					
15. Elevation (Show whether DF, KT, GR, etc.) 4426			12. County Chaves		
16. Check	Appropriate Box To Indicate N	ature of Notice, Report or Otl	her Data		
NOTICE OF INTENTION TO: SUBSEQUENT			REPORT OF:		
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CABING	PLUG AND ABANDON	CASING TEST AND CEMENT JQB	ALTERING CASING PLUG AND ABANDONMENT		
OTHER			in the description and provided		
 Describe Proposed or Completed Of work) SEE RULE 1103. 	perations (Clearly state all pertinent deta	ils, and give pertinent dates, including			

Well to be carried as temporarily abandon pending completion of Rock Queen Unit evaluation. 18. I hereby certify that the information above is true and complete to the best of my knewledge and belief. 7-28-87 ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR 0.1 n. 11 2-1-88