				Form C-103
OF COPIES RECEIVED	<u>'</u>			Supersedes: Old
DISTRIBUTION ANIA FE NEW MEXICO OIL CONSERVATION COMMISSION			C-102 and C-103 Effective 1-1-65	
SANTAFE		NEW WEXICO DIL CONS	ERVATION COMMISSION	Fliedding 1-1-03
FILE				5a. Indicate Type of Lease
U.S.G.S.				State XXX Fee
LAND OFFICE				5. State Oil & Gas Lease No.
OPERATOR		3,	0-005-00843	E-5663
	CUND DV N			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BALK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUC. PROPOSALS.)				
WATER INJECTION WELL				7. Unit Agreement Name ROCK QUEEN UNIT
WELL WELL OTHER-				8, Farm or Lease Name
2. Name of Operator				TRACT NO. 25
GREAT WESTERN DRILLING COMPANY				9. Well No.
3. Address of Operator				2 4-12
P.O.BOX 1659 MIDLAND TX 79701				10. Field and Pool, or Wildcat
4. Location of Well UNIT LETTER L 1980 FEET FROM THE SOUTH LINE AND 660 FEET FROM				CAPROCK QUEEN
UNIT LETTER				
THE WEST LINE, SECTION 24 TOWNSHIP 13-S RANGE 31-E NMPM.				
THE	LINE, SECTION			
mmm	mmm	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County
(1)				CHAVES
16.	Check App	ropriate Box To Indicate N	lature of Notice, Report or Ot	her Data
NC	TICE OF INTE		SUBSEQUEN'	T REPORT OF:
110	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
PERFORM REMEDIAL WOR	, \square	PLUG AND ABANDON	MEMEDIAL WORK	ALTERING CASING
			COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT XX
TEMPORARILY ABANDON	H	CHANGE PLANS	CASING TEST AND CEMENT JQB	
PULL OR ALTER CASING		Lamend	OTHER	[_]
OTHER				
			i la	a actimated date of starting any proposed
17. Describe Proposed (work) SEE RULE !	or Completed Operat	ions (Clearly state all pertinent det	ails, and give pertinent dates, therauliq	g estimated date of starting any proposed
work, see note:				
NMOCC noti	fied 24 hour	s prior to setting bo	thom plug.	
1-31-76 RI	J Csg. pulle	rs. Ran tbg & tagged	bottom @ 3000'. Spotte	ed 25 sx plug 3000'-2677'
W	OC 2 hrs. R	an wireline meas. & t	agged bottom @ 3000'(no	plug). Spotted 2nd
2.	5 sx plug 30	0 0-2677'. Pulled 30	jts tbg.	_
2-2-76 Ra	n wireline m	eas. & tagged plug @	2108'. Pulled & stretch	ned tbg. Tubing stuck
@ 1620'. Shot tbg @ 2082'. 1904' & 1608'. Pulled tbg. loose @ 1608'. Left				
1	7 its 2-3/8"	N-80 tbg(500') in ho	le. Displaced hole from	m 1608 ' w/ 25 #/bbl. salt
g	el mud. Pul	led tbg.		
2-3-76 RU csg jacks. Stretched csg & shot csg @ 1086'. Rec. 35 jts (1085') of 4½"OD 9.5#/ft. csg. Set 20 sx plug 1136' 1030'. Set 30 sx plug 297'-195'. Set 10 sx				
P	ing de surte			
PLUGGED AN	D ABANDONED	2-3-76.		
2230022 110				
			•	
	A	ove is true and complete to the best	of my knowledge and belief.	
18. I hereby cerulfy tha	t the information an	ove is true and complete to the best		
ا ال	1/1/1/1/1/1/		General Superintendent	2-11-76
SIGNED ()	YUME! Y	Y[TLE	General Superincendent	DATE
	C.5.			NOV 5 1976
	*		•	MA O 121A