| NO. OF COPIES RECEIVE DISTRIBUTION SANTA FE | | EW MEXICO OIL CONSERVA | Form C-103 Supersedes Old C-102 and C-103 Effective 1-1-65 | |
|--|--|--|--|--|
| U.S.G.S. LAND OFFICE | | | | State X Fee 5. State Oil & Gas Lease No. |
| OPERATOR | | | | B-8822 |
| | SUNDRY NOTICES | AND REPORTS ON WELL | .\$ | |
| | S FORM FOR PROPOSALS TO DR: USE "APPLICATION FOR PERMIT | LL OR TO DEEPEN OR PLUG BACK TO ' (FORM C-101) FOR SUCH PROPO | A DIFFERENT RESERVOIR. SALS.) | 7, Unit Agreement Name |
| | GAS OTHER. | | | 7. Ont Agreement Name |
| 2. Name of Operator | | · · · · · · · · · · · · · · · · · · · | | 8. Farm or Lease Name Tr. 15 |
| Weldon S. Gues | Drickey Queen Sd Unit/ | | | |
| 3. Address or Operator | ts & Gas Services. | Inc., Box 763, Hobi | s. New Mexico | 1 |
| 4. Location of Well | | 21.04, 201. 700, 1100. | og new nextee | 10. Field and Pool, or Wildcut |
| UNIT LETTER |) 660 FEE | ET FROM THE South | 1980 F | Caprock Queen |
| THE East | LINE, SECTION | TOWNSHIP 13 S | | _ NMPM. |
| | 111111111111111111111111111111111111111 | Elevation (Show whether DF, RT | , GR, etc.) | 12. County |
| <u>(† 1111)</u> | | Box To Indicate Nature | | Chaves |
| TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed o work) SEE RULE 11 | r Completed Operations (Clear o3. It is proposed to Set cast iron bri Cut & pull 5 1/2' Spot 100' plug ac Spot 100' plug ac Spot 100' plug ac Spot 100' plug ac | change Plans casing of plug as follows: idge plug @ 3000 & casing from 2000 cross casing stub cross top of salt @ 1 cross 8 5/8" shoe @ 3 cross 8 5/8" sh | ap with 3 sack 1500 302 | including estimated date of starting any proposed |
| | | HOI PLU TO | JRS PRIOR TO T GGING OPERATIO BE APPROVED. | UST BE NOTIFIED 24 HE BECKNING OF NS FOR THE C-103 |
| 18. I hereby certify that | the information above is true | and complete to the best of my kr | nowledge and belief. | |
| Man es | alleller | ,,,,, E A | gent | DAYE 10/10/73 |
| SIGNED / | | 11105 | | |

CONDITIONS OF APPROVAL, IF ANY: