

COPIES RECEIVED		
CONTRIBUTION		
NOTES		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-6401
7. Unit Agreement Name
8. Farm or Lease Name Drickey Queen Sand Unit Tr 38A
9. Well No. 6
10. Field and Pool, or Wildcat Caprock Queen
12. County Chaves

30-005-00918

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Injection Well</b>
2. Name of Operator Weldon S. Guest & I. J. Wolfson
3. Address of Operator c/o Oil Reports & Gas Services, Inc., Box 763, Hobbs, N.M.
4. Location of Well UNIT LETTER <b>J</b> <b>1980</b> FEET FROM THE <b>South</b> LINE AND <b>1980</b> FEET FROM THE <b>East</b> LINE, SECTION <b>35</b> TOWNSHIP <b>13 S</b> RANGE <b>31 E</b> N.M.P.M.
15. Elevation (Show whether DF, RT, GR, etc.) <b>4411 DF</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Subject well plugged and abandoned 11/7/73 as follows:

Set cast iron bridge plug @ 2875 & capped with 5 sacks cement.  
Cut & pulled 5 1/2" casing from 1215.  
Spotted plug from 1215 to 1315 with 25 sacks.  
Spotted plug from 275 to 375 with 25 sacks.  
Set 10 sack plug at surface with regulation marker.  
10.1# mud (visc. 32) between all plugs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>John W. Runyan</u>	TITLE <u>Agent</u>	DATE <u>11/16/73</u>
APPROVED BY <u>John W. Runyan</u>	TITLE <u></u>	DATE <u></u>
CONDITIONS OF APPROVAL, IF ANY:		