

COPIES RECEIVED		
TRIBUTION		
IT'S FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

30-005-00921

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-5988	
7. Unit Agreement Name	
8. Farm or Lease Name Drickey Queen Sand Unit Tr 37	
9. Well No. 1	
10. Field and Pool, or Wildcat Caprock Queen	
12. County Chaves	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT L" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Injection Well
2. Name of Operator Weldon S. Guest & I. J. Wolfson
3. Address of Operator c/o Oil Reports & Gas Services, Inc., Box 763, Hobbs, N.M.
4. Location of Well UNIT LETTER F , 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 35 TOWNSHIP 13 S RANGE 31 E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4410

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Subject well plugged and abandoned 11/6/73 as follows:

Set cast iron bridge plug @ 2623 & capped with 5 sacks cement.
Shot & pulled 5 1/2" casing from 1185.
Spotted plug from 1185 to 1285 with 25 sacks.
Spotted plug from 200 to 300 with 25 sacks.
Set 10 sack plug at surface with regulation marker.
10.1# mud (visc. 32) between all plugs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *L. Emma Kellis* TITLE Agent DATE 11/16/73

APPROVED BY *Nathan E. Clegg* TITLE Commissioner DATE _____

CONDITIONS OF APPROVAL, IF ANY: