Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, minerals and Natural Resources Department

Form C-103

DISTRICT I P.O. Box 1980, Hob				
1.O. Dox 1700, 110	hhe NIM 88240	- · · · · · ·	TION DIVISION	WELL API NO.
1.O. DOX 2000				30-005-00923
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088			5. Indicate Type of Lease	
DISTRICT III				STATE XX FEE
	d., Aztec, NM 87410	20 00		6. State Oil & Gas Lease No.
	OUNDRY NOT		5-00923	E-5988
(DO NOT USE 1		ICES AND REPORTS ON OPOSALS TO DRILL OR TO DE		7. Lease Name or Unit Agreement Name
,	DIFFERENT RESEF	RVOIR. USE "APPLICATION F	OR PERMIT"	7. Lease Name of Onk Agreement Name
1. Type of Weil:	(РОНИ С-	-101) FOR SUCH PROPOSALS	5.)	Drickey Queen Sand Unit
OIL WELL	GAS WELL	OTHER	Triogtion	Tract 37
2. Name of Operat		- Onex	Injection	8. Well No.
•	Ridge Product	3		
3. Address of Operator				9. Pool same or Wildcat
	ox 755 Hobbs.	NM 88240		Caprock Queen
4. Well Location		37 1		
Unit Lette	er <u>B</u> : 660	Feet From TheNorth	1 Line and 198	Feet From The East Lin
Cartian	35	Township 13S	Range 31E	NMPM Chaves County
Section (////////////////////////////////////			Range 31E whether DF, RKB, RT, GR, etc.)	V/////////////////////////////////////
11.	Check	Appropriate Box to Indi	cate Nature of Notice, R	eport, or Other Data
N	NOTICE OF INT	ENTION TO:	SUE	SEQUENT REPORT OF:
PERFORM REMED	DIAL WORK L	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY AB	BANDON	CHANGE PLANS	COMMENCE DRILLING	G OPNS. L. PLUG AND ABANDONMENT
PULL OR ALTER O	CASING		CASING TEST AND C	EMENT INR
				-
OTHER:			OTHER: Tempo	prarily Abandon
work) SEE RU	Requ		ell be placed in a t). Last injection N	emporarily abandoned
SIGNATURE	Manual Va	e and complete to the best of my knowledge. LL1 Y JERRY SEXTON PERVISOR	odge and belief. TITLEAgent	DATE 3/6/90 TELEPHONE NO. MAR 1 2 1990

TA expire 2-1-91

RECEIP FOR

MAR 9 155

OCE HOBBS CAFALL