STATE OF NEW					-	•	,				
, 	Y AND MINERALS DEPARTMENT OIL CONSERVATION DIVISION						Sa. In	Sa. Indicate Type of Lease			
40. 07 10*110 0111110				P. O. BOX 2088				State X Fee			
SANTA FE	DISTRIBUTION CANTA SE NEW MEXICO 87501					5. 5ic	ite Oil & Gir	. Leune No.			
FILE				_							
WELL COMPLETION OR RECOMPLETION REPORT AND LOG								TITTI	TITITITI TO		
LAND OFFICE											
OFFRATOR								II Agreemen	1 Nome		
10. TYPE OF WELL											
D. TYPE OF COMPLETION								Rock Queen Unit 36			
NEW WORK DEEPEN PLUG DIFF. OTHER P & A											
2. Name of Operator								9. Well No.			
Great Western Drilling Company								10. Field and Pool, or Wildcat			
3. Address of Operator P.O. Box 1659, Midland, Texas 79702								Caprock Queen			
4. Location of Well											
UNIT LETTER H	LOCATED . 6	660 FEET F	OM THEE	ast	LINE AND	1,980 rec	T FROM 12. C	777777			
							/////				
THE North LINE OF	sec. 36	wp. 13-5 mg	: 31-E	NMPM	777777	IIXIIIII		aves	<u> </u>		
15. Date Spudded	16. Date T.D. Re	eached 17. Date	Compl. (Read	ly to Prod	-	evations (DF, RK		1			
1-5-56	1-19-5		1-24-56			34.1' GR, 4		4,38	3.1 ′ able Tool≢		
: 3. Total Depth	21. Pluq	Back T.D.	22. If N		ompl., How	Daillad D	Rotary Tool	:			
3,067'							0-3,025		,025'-3,067' as Directional Surve		
24. Producing interval	s), of this completi	ion - Top, Bottom	, Name					23. M	ade		
•								ł			
								27, Was Well Cored			
20. Type Electric and C	Other Logs Run		•				•	27. Wds W	en corea		
								<u> </u>			
18.		CAS	ING RECORD	(Report	all strings s						
CASING SIZE WEIGHT LB./F			<u></u>			E SIZE CEMENTING RE					
8 5/8" 24		303		2 1/4" 200 S2 7 7/8" 100 S2							
5 ¹ 2"	14	14 3,061		1 //	//8") Sxs.		900		
			ER RECORD			30.			TUBING RECORD		
19.							DEPTH SET		PACKER SET		
SIZE .	тор	BOTTOM	SACKS CEN	ENI	SCREEN		, J				
			!		2 4	CID SHOT ERA	CTURE CEME	NT SQUEE?	ZE. ETC.		
31. Perforation Record (Interval, size and number) 32. ACID, SHOT, FRACTURE								OUNT AND KIND MATERIAL USED			
4 3/4" Open hole 3,061'-3,067'											
4 3/4 Open note 3,001 3,001											
											
			 :-	PRODUC	TION						
33.	Dr.wi	ction Method /Flor	wing, gas life			type pump)	Wei	1 Status (Pr	od or Shurray		
Dote First Production Production Method (Flowing, gas lift, pumping - Size and type pump)							1		Abandoned		
Pale of Test	Hows Tested	Choke Size	Prod'n. Fe	or Oil	- Bbl.	Gas - MCF	Water - B		-Oil Batto		
1 310 01 7021			Test Perio	∞d			1	- 1			
Flow Tubing Press.	Cosing Pressure		- OII - Bbl.		Gas - MC	F Wate	- Bbl.	Oil Gray	ILLY - API (Corr.)		
		Hour Rate	.		}						
14. Disposition of Gas (Sold, used for fuel, vented, etc.)								essed By			
				=							
35. List of Attachments	· ·										
36. I hereby certify tha	the information s	hown on both side	s of this form	is true a	nd complete	to the best of my	knowledge on	1 belief.			
nouse M	1. My			E Ass	s't. to	Gen. Supt.	DAT	E3-	-21-83		
SIGNED //	1.7										

RECEIVED

MAR 23 1983

HOBES OFFICE