

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
5. State Oil & Gas Lease No. E-2855	
7. Unit Agreement Name D. Q. S. U.	
8. Farm or Lease Name Tract 32	
9. Well No. 1	
10. Field and Pool, or Wildcat Caprock Queen	
12. County Chaves	

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS</p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)</small></p>	
<p>1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/></p>	
<p>2. Name of Operator Cities Service Oil Company</p>	
<p>3. Address of Operator Box 69 - Hobbs, New Mexico 88240</p>	
<p>4. Location of Well UNIT LETTER B , 330 FEET FROM THE North LINE AND 2310 FEET FROM THE East LINE, SECTION 2 TOWNSHIP 14S RANGE 31E NMPM.</p>	
<p>15. Elevation (Show whether DF, RT, GR, etc.) 4412' GR</p>	

<p>16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data</p>	
<p>NOTICE OF INTENTION TO:</p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>	<p>SUBSEQUENT REPORT OF:</p> <p>PLUG AND ABANDON <input checked="" type="checkbox"/></p> <p>CHANGE PLANS <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We propose to plug and abandon the above well in the following manner:

- 1. Set CI bridge plug in casing just above open hole. (5½' set @ 3125 w/125 sxs)**
- 2. Set 25 sack cement plug on top of bridge plug.**
- 3. Load hole with mud laden fluid.**
- 4. Set 10 sack cement surface plug with a 4" dry hole marker.**
- 5. Clean location of all debris and equipment.**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ORIGINAL SIGNED
C. D. ROBINSON

SIGNED _____ TITLE **District Admin. Supervisor** DATE **5/4/70**

APPROVED BY _____ TITLE **SUPERVISOR DISTRICT** DATE **MAY 7 1970**

CONDITIONS OF APPROVAL, IF ANY:

MAY 5 1970

RECEIVED

MAY 6 1970

OIL CONSERVATION COM. L.
HOBBES, N. H.