

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
----------------------------	------------------------------------------------------------------------

5. State Oil & Gas Lease No.	E-7661
------------------------------	---------------

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Water Injection	7. Unit Agreement Name D.Q.S.U.
2. Name of Operator Cities Service Oil Company	8. Farm or Lease Name Tract 40
3. Address of Operator Box 69 - Hobbs, New Mexico	9. Well No. 2
4. Location of Well UNIT LETTER F , 1980 FEET FROM THE North LINE AND 1650 FEET FROM THE West LINE, SECTION 2 TOWNSHIP 14S RANGE 31E NMPM.	10. Field and Pool, or Wildcat Caprock Queen
15. Elevation (Show whether DF, RT, GR, etc.) -	12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The above well was plugged and abandoned on 6/17/70 in the following manner:

1. Set a CI bridge plug @ 2930. (7" set @ 3069 w/125 sxs)
2. Set a 25 sack cement plug on top of bridge plug @ 2930-2805.
3. Loaded hole with mud laden fluid.
4. Set a 10 sack cement surface plug @ 30-0 with a 4" marker extending 4' above the surface to designate a P & A location.
5. Location has been cleared of all debris and equipment and is ready for final inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>ORIGINAL SIGNED C. E. ROBERTSON</u>	TITLE <u>District Admin. Supervisor</u>	DATE <u>1/20/71</u>
APPROVED BY <u>John W. Remyan</u>	TITLE <u>Geologist</u>	DATE <u>FEB 16 1971</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

FEB 12 1971

OIL CONSERVATION COMM.
HOUSTON, TEX.