

NO. OF COPIES RECEIVED	
DISTRIBUTION	
DATE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.
E-5665

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER P & A 30-005-00958	7. Unit Agreement Name
2. Name of Operator Weldon S. Guest & I. J. Wolfson	8. Farm or Lease Name Drickey Queen Sand Unit Tr 35
3. Address of Operator c/o Oil Reports & Gas Services, Inc., Box 763, Hobbs, New Mexico	9. Well No. 1
4. Location of Well UNIT LETTER A , 330 FEET FROM THE North LINE AND 990 FEET FROM THE East LINE, SECTION 2 TOWNSHIP 14 S RANGE 31 E NMPM. Caprock Queen	10. Field and Pool, or Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 4408 GR	12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER Re-enter & salvage casing <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Re-entered and shot off 5 1/2" casing at 2020.
Spotted 100' plug 2000 to 2100 with 30 sacks.
Spotted 100' plug 1500 to 1600 with 30 sacks.
Spotted 100' plug 250 to 350 with 30 sacks.
Set 10 sack plug at surface with regulation marker.
10.1# mud (visc. 32) between all plugs.
Work complete 10/27/73.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *W. S. Guest* TITLE Agent DATE 10/30/73
APPROVED BY *John W. Runyan* TITLE Chairman DATE 10/30/73
CONDITIONS OF APPROVAL, IF ANY: