Budget	Bureau	No.	42-R358.4.
Approv	al expire	s 12	-31-60.

'orm 9-331a	х.	inpproval capito iz ar 60,
(Feb. 1951)	(SUBMIT IN TRIPLICATE)	Land Office
x	UNITED STATES	Lease No.
	n stand e sala di esta	

SUNDRY NOTICES AND REPORTS ON WELLS

John H. Trigg Federal Trigg Lease /	and a start of the		Harch 1		, <u>19_</u> 60
(indic	CATE ABOVE BY CHECK M	ARK NATURE OF REPOR	RT, NOTICE, OR OTHER D	DATA)	
NOTICE OF INTENTION TO PULL OR NOTICE OF INTENTION TO ABANDON		SUPPLEMEN CONVER	TARY WELL HISTORY	Injection	x
NOTICE OF INTENTION TO SHOOT O			REPORT OF ABANDON	MENT.	
NOTICE OF INTENTION TO TEST WA			REPORT OF ALTERING	ING OR REPAIR	
NOTICE OF INTENTION TO CHANGE			REPORT OF SHOOTING	-	

The elevation of the derrick floor above sea level is _____ ft. 4304° 5.2.

DETAILS OF WORK

(State name	s of and expected dep	ths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cement ing points, and all other important proposed work)	t
Tì	his well was	reported as a gas well with a petential of 1,600,000	
CFPD in	n May, 1959.	Tubing was pulled and well hore cleaned out to TD of	
2724 ;	g.l. on July	22, 1959. Casing was perforated from 2684' to 2694'	
		Paylowated interval to date is 26841-26981 On July 21	

a 1959 we ran 2664.7' of 2" EUE 8rd. thd. 4.7% Sals. Cement Lined tubing and a 1959 We ran 2664.7' of 2" EUE 8rd. thd. 4.7% Sals. Cement Lined tubing and a 1989 9.5% Guiberson "Shorty Ten" tension type packer. Packer and tubing are open ended. Facker was landed and see at 2665.5' g.l. Facker was tested for leaks by applying 1000 pei pressure on anulus. No leaks found. Injection mainfold was hooked up July 22, 1959 and injection of water into the Queen formation was begun 3:00 P.M. WST August 1, 1959.

Injection rate of approximately 400 Barrels of water per day was established and has been maintained to this date.

1 -

	that this plan of work must receive approval in writing JOHN H. TRIGS COMPANY		before op erations may be com	menced.
	BOX 106			
Address	NALJAMAR, NEW MEXICO	By	۰,	!
		2	d. Supt.	

GPO 862040