

COPIES RECEIVED	
CONTRIBUTION	
FEE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

30-005-01002

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
D-10411	
7. Unit Agreement Name	
Track #1	
Queen Sand Unit	
8. Farm or Lease Name	
Track #1	
Queen Sand Unit	
9. Well No.	
2	
10. Field and Pool, or Wildcat	
Caprock Queen	
12. County	
Chavez	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator
Wolfsen Oil Company	Chaves Oil Ltd.
3. Address of Operator	4. Location of Well
Wichita Falls, Texas; 1000 Oil & Gas Building	UNIT LETTER A, 990 FEET FROM THE North LINE AND 330 FEET FROM THE East LINE, SECTION 8 TOWNSHIP 14-S RANGE 31 B NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)	16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
4109	NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

PLUG AND ABANDON	<input checked="" type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

REMEDIAL WORK	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>
CASING TEST AND CEMENT JOBS	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

ALTERING CASING	<input type="checkbox"/>
PLUG AND ABANDONMENT	<input checked="" type="checkbox"/>
OTHER	<input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-6-73 5 1/2" CIBP at 2500' Dump 5 sacks cement on plug 42.5' fill in 14# 5 1/2 T.O.C. 5' Cut 5 1/2 at 2020', Work pipe Cut at 1474' Work pipe. Shut down for night. Load annulus with fresh water.

12-7-73 Work pipe shot at 1180' work pipe. shoot at 685'. Pull out of hole. with 5 1/2". Run 2-3/8" tubing to 740'. Spot 35 sack from 740' to 640. Pull to 120' Spot 35 sack across 8-5/8" shoe. Mud between all plugs. Pull out of hole. Spot 10 sack surface plug. Rig down move off.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Richard D. Conn

Field Superintendent

12-31-73

SIGNED

TITLE

DATE

APPROVED

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: