

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-10420
7. Unit Agreement Name D. Q. S. U.
8. Farm or Lease Name Tract 25
9. Well No. 1
10. Field and Pool, or Wildcat Caprock Queen
12. County Chaves

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Water Injection
2. Name of Operator Cities Service Oil Company
3. Address of Operator Box 69 - Hobbs, New Mexico 88240
4. Location of Well UNIT LETTER J , 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 16 TOWNSHIP 14S RANGE 31E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4306 DF

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data


NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We propose to plug and abandon the above well in the following manner:

- Set CI bridge plug in casing just above open hole. (7" set @ 2856 w/125 sxs)**
- Set 25 sack cement plug on top of bridge plug.**
- Load hole with mud laden fluid.**
- Set 10 sack cement surface plug with a 4' dry hole marker.**
- Clean location of all debris and equipment.**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ORIGINAL SIGNED C. D. ROBERTSON	TITLE District Admin. Supervisor	DATE 5/4/70
SIGNED 	TITLE SUPERVISOR DISTRICT	DATE MAY 7 1970
APPROVED BY		
CONDITIONS OF APPROVAL, IF ANY:		

OIL CONSERVATION COMM.
HOBBS, N. M.

MAY 6 1970

RECEIVED

RECEIVED

MAY 2

1970