NO, OF COPIES RECE	IVED		Form C-103		
DISTRIBUTIO			Supersedes Old		
SANTA FE	<u></u>	O OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65		
FILE					
U.S.G.S.			5a. Indicate Type of Lease		
LAND OFFICE			State Fee 🗶		
OPERATOR			5. State Oil & Gas Lease No.		
(DO NOT USE	THIS FORM FOR PROPOSALS TO DRILL OR TO DE USE "APPLICATION FOR PERMIT*" (FORM	EPORTS ON WELLS EPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. C-1011 FOR SUCH PROPOSALS.)			
1.			7. Unit Agreement Name		
OIL WELL	D.Q.S.U.				
2. Name of Operator	8. Farm or Lease Name				
Citie	Tract 20				
3. Address of Operat	9. Well No.				
Box 6	1				
Box 69 - Hobbs, New Mexico 88240 4. Location of Well			10. Field and Pool, or Wildcat		
	1980	E South LINE AND 660 FEET FROM	Caprock Queen		
UNIT LETTER	FLET FROM TH	E FEET 100			
Wes	+ 16	SHIP 145 RANGE 31E NMPM.			
THE	LINE, SECTION TOWN	SHIP RANGE NMPM.			
<u>uuuuuu</u>	15. Elevation	(Show whether DF, RT, GR, etc.)	12. County		
())))))))))))))))))))))))))))))))))))		4165 DF	Chaves		
<u>16.</u>	Clush Appendicts Boy T	o Indicate Nature of Notice, Report or Otl	her Data		
	NOTICE OF INTENTION TO:		REPORT OF:		
	NOTICE OF INTENTION TO:				
		D ABANDON REMEDIAL WORK	ALTERING CASING		
PERFORM REMEDIAL		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT		
TEMPORARILY ABAND					
PULL OR ALTER CAS!					
OTHER					
17, Describe Propos	ed or Completed Operations (Clearly state of	ill pertinent details, and give pertinent dates, including	estimated date of starting any proposed		
work) SEE RUL	E 1103.				
The above well was plugged and abandoned in the following manner: (plugged 6-8+70)					
ine a	DOVE WELL Was progyed and	and the che for the first of the second	·· (Prugged 0-0-70)		
1	Sat - Cl Bridge Blug @ 276	50 (7" set @ 2795 w/125 sxs)			
1.	Set a ti biluge riug e 2/0				
•	a set a at and amont alug on top of heldge plug @ 2760=2645				
۷.	2. Set a 25 sack cement plug on top of bridge plug @ 2760-2645.				
a traded halo when much lodon fluid					
3. Loaded hole with mud laden fluid.					
L.	4. Set a 10 sack cement surface plug @ 30-0 with a $4^{11}$ marker extending				
4.	4. Set a 10 sack cement surface plug @ 30-0 with a 4" marker extending				
		alanate a R & A location			
	4 <sup>1</sup> above the surface to de	ssignaças a r a A location.			
_	· · · · · · · · · · · · · · · · · · ·	at all debute and equipment and	is ready for		
5.	Location has been cleared	of all debris and equipment and	is leady ion		
	final inspection.				
18. I hereby certify	that the information above is true and comp	lete to the best of my knowledge and belief.			
	RICO ISL JONED	Bladelad Adala Cunamitra	DATE 11/12/70		
SIGNED	0. ROSSALOON	TITLE District Admin. Supervisor			
			and and the second s		
()	I A A		FEB 2 1 1971		
	The lef. IN MANULAN	TITLE	DATE		

TITLE \_\_\_\_\_\_ POIOgist

APPROVED BY	Ruman
CONDITIONS OF APPROVAL, IF	

• • • • • • • • • • • • • • • •

(1,2) = (1,2) + (1,2

• • RECEIVED

JAN CO 1971 OIL CONSERVATION COMM. HOSED, N. I.-

and the second second