	<u>*</u> * ·				
	ž,			*. <del></del>	
DISTRIBUTION ANTA FE	NEW ME	XICO OIL CONSER	VATION COMMISSION		Form C-103 Supersedes Old C-102 and C-103 Effective 1-1-65
ILE				F3	M
J.S.G.S.	7			5	State X Fee
AND OFFICE	_			<u> </u>	
PERATOR				1	5, State Oil & Gas Lease No.
PERATOR		_			
SUNE	ORY NOTICES AND	REPORTS ON WI	ELLS ( TO A DIFFERENT RESERV PROPOSALS.)	olr.	
USE AFFEIG	ATTON FOR PERMIT - (				7. Unit Agreement Name
OIL GAS	OTHER-				D. Q. S. U.
WELL WELL WELL	OTHER-				8. Farm or Lease Name
2. Name of Operator Cities Service Dil Company					Tract 33
Cition Service	611 Gambani				9. Well No.
40					••
. Address of Operator	4	3240			 _
Box 69 - Habbs,	4	3240			10. Field and Pool, or Wildcat
Box 69 - Hebbs, Location of Well	New Mexico 85		1980		 _
Box 69 - Habbs,	4	South	LINE AND 1980		10. Field and Pool, or Wildcat
Box 69 - Hebbs,  Location of Well  UNIT LETTER K	New Mexico 88		_ LINE AND		10. Field and Pool, or Wildcat
Box 69 - Hebbs,  Location of Well  UNIT LETTER K	New Mexico 88	M THE South	RANGE 31E	FEET FROM	10. Field and Pool, or Wildcat
Box 69 - Hebbs,  Location of Well  UNIT LETTER K	New Mexico 88	TOWNSHIP 148	RANGE 31E	FEET FROM	10. Field and Pool, or Wildcat  Caprock Queen
Box 69 - Hebbs,  . Location of Well  UNIT LETTER K  THE West LINE, SEC	New Mexico 88	TOWNSHIP 148 ation (Show whether DI	F, RT, GR, etc.)	_ FEET FROMNMPM.	10. Field and Pool, or Wildcat  Caprock Queen  12. County  Chaves
Box 69 - Hebbs,  . Location of Well  UNIT LETTER K  THE West LINE, SECONOTICE OF NOTICE OF	New Mexico 88  1980  FEET FROM  15. Eleventh of the second	TOWNSHIP 148  ation (Show whether DI 4184 GR  X To Indicate Na	F, RT, GR, etc.)  ture of Notice, Re  SU  REMEDIAL WORK COMMENCE DRILLING OPN:	PORT OF OTH	10. Field and Pool, or Wildcat  Caprock Queen  12. County  Chaves  Chaves
Box 69 - Hebbs,  Location of Well  UNIT LETTER K  THE West LINE, SEL  16. Check NOTICE OF	New Mexico 88  1980  FEET FROM  15. Eleven  k Appropriate Box INTENTION TO:	TOWNSHIP 148  ation (Show whether DI 4184 GR  X To Indicate Na	F, RT, GR, etc.)  ture of Notice, Re SU	PORT OF OTH	10. Field and Pool, or Wildcat  Caprock Queen  12. County  Chaves  er Data  REPORT OF:  ALTERING CASING
Box 69 - Hebbs,  Location of Well  UNIT LETTER K  THE West LINE, SER  Check NOTICE OF  PERFORM REMEDIAL WORK TEMPORARILY ABANDON	New Mexico 88  1980  FEET FROM  16  15. Eleven  k Appropriate Box INTENTION TO:	TOWNSHIP 148  TOWNSHIP 148  A184 GR  X TO Indicate Na  JIG AND ABANDON 18  ANGE PLANS 19	RANGE 31E  F, RT, GR, etc.)  ture of Notice, Re SU  REMEDIAL WORK  COMMENCE DRILLING OPN: CASING TEST AND CEMENT	PORT OF OTH	10. Field and Pool, or Wildcat  Caprock Queen  12. County  Chaves  er Data  REPORT OF:  ALTERING CASING  PLUG AND ABANDONMENT

We propose to plug and abandon the above well in the following manner:

- Set CI bridge plug in casing just above open hole. (7" set @ 2833 w/125 sxs) 1.
- Set 25 sack cement plug on top of bridge plug. 2.
- Load hole with mud laden fluid. 3.

<b>3.</b>	Ford those with war seast states					
4.	Set 10 sack coment surface plug with a 4" dry hole marker.					
5.	Clean location of all debris and equipment.					
	ify that the information above is true and complete to t	he hest of my knowledge and belief.				
parent of the	er 15 <b>D</b>	LE Bistrict Admin. Supervisor	DATE 5/4/70			
1000	Line Am	SEPERVISOR DISTRICT	MAY 7 1976			
APPROVED BY	F APPROVAL, IF ANY:	LE SUPRVISOR DISTRICT				

ONT CONSESSED TO

. - Mar

0781 3 YAM

RECEIVED