

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

30-005-01137

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CLEAN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

7. Unit Agreement Name

8. Farm or Lease Name

East Cap Queen Unit

9. Well No.

1 3

10. Field and Pool, or Wildcat

Caprock Queen

12. County

Chaves

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER: **Temporarily Abandoned**
2. Name of Operator
Rapid Company, Inc.
3. Address of Operator
c/o Oil Reports & Gas Services, Inc., Box 763, Hobbs, New Mexico 88240
4. Location of Well
UNIT LETTER **M** **330** FEET FROM THE **South** LINE AND **330** FEET FROM
THE **West** LINE, SECTION **23** TOWNSHIP **14 S** RANGE **31 E** NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged & abandoned 2/16/75:

Set cast iron bridge plug @ 3000' & capped with 35' cement
Cut & pulled 4 1/2" casing from 698'
Spotted 100' plug @ 698'
Spotted 100' plug across 8 5/8" casing shoe @ 176'
Set 10 sack plug @ surface with regulation marker
Mud between all plugs
Location cleared, levelled & ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Harvey Heller TITLE Agent DATE 6/17/76
APPROVED BY John Runyan TITLE Geologist DATE NOV 1976
CONDITIONS OF APPROVAL, IF ANY: