

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Water Injection		7. Unit Agreement Name Eastcap Queen Pool Unit
2. Name of Operator AGUA, INC.		8. Farm or Lease Name
3. Address of Operator Box #198, Artesia, New Mexico 88210		9. Well No. 13
4. Location of Well UNIT LETTER J . 1650 FEET FROM THE South LINE AND 2310 FEET FROM THE East LINE, SECTION 27 TOWNSHIP 14 South RANGE 31 East NMPM.		10. Field and Pool, or Wildcat Caprock Queen
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This is a shut-in water injection well. The following plugging program was approved by Mr. Ramey by phone on Dec. 13, 1973. It is proposed to proceed with plugging and abandoning as follows:

Total Depth - 3110'.
Surface Casing - 8-5/8" at 259' w/150 sx.
Prod. Casing - 4 1/2" 9.5# at 3086' w/75 sx.
Perforations - 3086-3110 (OH)
Tubing - 3086' w/tension packer.
Top of Salt - 1500'.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

Plugging Program

- Proceed with either Option A or B.
Option A - Set bridge plug above perforations and cap with 35' cement.
Option B - Place 100' cement plug above perforations.
- Cut oil casing off. Place 100' cement plug at top of stub. If stub is below top of salt, place 100' cement plug at top of salt.
- Place 100' cement plug to straddle bottom of surface casing.
- Cap with 10 sacks cement.

Mud hole during plugging procedure. Notify Oil Commission at start of operations.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ralph L. Gray TITLE Consulting Engineer. DATE Dec. 13, 1973

APPROVED BY Joe D. Ramey TITLE Dir. of Cons. DATE

CONDITIONS OF APPROVAL, IF ANY: