

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. LC 6477

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name So. Caprock Queen Unit
2. Name of Operator Union Oil of California	8. Farm or Lease Name So. Caprock Queen Unit
3. Address of Operator 500 N. Maricopa - Midland, Texas	9. Well No. T-44A, W-16, Se 32
4. Location of Well UNIT LETTER <u>1</u> FEET FROM THE <u>5</u> LINE AND <u>600</u> FEET FROM THE <u>32</u> LINE, SECTION <u>32</u> TOWNSHIP <u>14S</u> RANGE <u>31 E</u> NMPM.	10. Field and Pool, or Wildcat So. Caprock Queen Unit
15. Elevation (Show whether DF, RT, GR, etc.) GL 4432'	12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging Procedures Below:

1. 8 5/8" # 280' w/175 Sx.
2. 5 1/2" # 3492' w/75 Sx.
3. Perf. & Open Hole 3101' - 3118'
Plug No. 1 - 25 Sx. # 3100'
Plug No. 2 - 25 Sx. # 5 1/2" Stub
Plug No. 3 - 35 Sx. # Base of Surface 280'
Plug No. 4 - 5 Sx. # Surface 10 SXS

Establish Dry Hole Marker

H. J. den, Inc.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Agent for Union Oil

SIGNED [Signature]

TITLE of California

DATE JUNE 16, 1971

APPROVED BY [Signature]

TITLE SUPERVISOR DISTRICT I

DATE JUN 25 1971

CONDITIONS OF APPROVAL, IF ANY:

DECLINED

JUN 8 1971

OIL CONSERVATION COMM.
WASH, D. C.

100-100000