		Form C-103
		Supersedes Old
S RECEIVED		C-102 and C-103
BUTION		
/BUTION	NEW MEXICO OIL CONSERVATION COMMISSION	
£		5a. Indicate Type of Lease
		State X Fee
·		5. State Oil & Gas Lease No.
OFFICE		
ATOR		
	OTICES AND REPORTS ON WELLS Is to drill or to deepen or plug back to a different reserve or permit - " (form C-101) for such proposals.)	
SUNDRY N	OTICES AND REPORTS ON WELLS A DIFFERENT RESERVE	01R.
DO NOT USE THIS FORM FOR PROPOSAL	DR PERMIT " (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
USE ATTEN		
GAS	Water Injection	8. Farm or Lease Name
	OTHER- WATEL INJECTION	
( O partor		
Miller & Miller Auct	cioneers, Inc.	9. Well No.
Miller & Miller Ade		20
Address of Operator		10. Field and Pool, or Wildcat
Location of Well	1090	FEET FROM Caprock Queen
Location of non	0FEET FROM THENorthline and1980_	
UNIT LETTER OD		
	34TOWNSHIP14 Southage31 E	ast NMPM. (
East LINE, SECTION _	34 TOWNSHIP 14 SOUCHANGE	
THEEASTLINE, SECTION	DE DE DE CR pic.)	12. County
	15. Elevation (Show whether DF, RT, GR, etc.)	
//////////////////////////////////////		
	propriate Box To Indicate Nature of Notice, Re	eport of Other Data
Check AD	propriate Box To Indicate Nature of Notice, R	JBSEQUENT REPORT OF:
6. Check Ap	SUTION TO:	JBSEQUENTINE
NOTICE OF INT	ENTION TO:	
	REMEDIAL WORK	
[_]	DILLIG AND ABARDON LES I	PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK	COMMENCE DRILLING OP	
TEMPORARILY ABANDON	CHANGE PLANS CASING TEST AND CEMEN	
PULL OR ALTER CASING	OTHER	
		proposed
OTHER	it and give pertipent (	dates, including estimated date of starting any property
Completed Oper	rations (Clearly state all pertinent details, and give pertinent of	
work) SEE RULE 1103.		
work) SEE RODE		
	Set bridge plug above perforat	ions and cap with 35' cement
	ast bridge plug above perforat	1001s and cup and coment plug
Plugging Program:	Set Dridge pres	ing. Place 100 Cemene 100'
FIGGGT	Set bridge plug above perforat Mud hole. Cut off 5 1/2" casi	alow top of salt, place 100
	at top of stud. II stud 10	in a loor cement plug to
	at top of salt.	Place IOU cement raise
	at top of stub. If stub is be cement plug at top of salt. I straddle bottom of 8 5/8" cas	ing. Cop with 10 sacks of
	straddle bottom of 8 5/8" cas cement. Notify Oil Commission	
	cement. Notify 011 Commission	724 hrs before setting
	Cellerot	AT AIS DUSING
		bottom plug.
	ement plags must be	and the three of Tubing
	the Alves Must be	SPOTTO IMPAUTA
All C	EMENI PUTTO THE SO	/
• • •	·	
	in a start	belief.
	n above is true and complete to the best of my knowledge and t	- ·
18. I hereby certify that the information	in above is the end on TITLE Vice Pres	udent_ DATE 10-14-74
	, 1/ Mico Pres	uaint DATE 10 1
ALV.	Mile TITLE VILLE I Jes	
SIGNED	www.	
	(Sector)	DATE
Lim	W. Umum TITLE	<u></u>
APPROVED BY		

CONDITIONS OF APPROVAL, IF ANY: