

N. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

<p><b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/></p>
<p>1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER</p>		<p>5. State Oil &amp; Gas Lease No.</p>
<p>2. Name of Operator <b>MILLER &amp; MILLER AUCTIONEERS, INC.</b></p>		<p>7. Unit Agreement Name <b>Eastcap Queen</b></p>
<p>3. Address of Operator</p>		<p>8. Farm or Lease Name <b>24</b></p>
<p>4. Location of Well UNIT LETTER <b>H</b> <b>1860</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>East</b> LINE, SECTION <b>34</b> TOWNSHIP <b>14 South</b> RANGE <b>31 East</b> NMPM.</p>		<p>9. Well No. <b>24</b></p>
<p>15. Elevation (Show whether DF, RT, GR, etc.)</p>		<p>10. Field and Pool, or Wildcat <b>Caprock Queen</b></p>
<p>16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:</p>		<p>12. County <b>Chaves</b></p>
<p>PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/></p>		<p>SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/></p>
<p>17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.</p>		

Set bridge plug above perforations and cap with 35' cement.  
Shot 4 1/2 casing at 623'. Set 100' cement plug. Place  
100' cement plug at bottom of 7 5/8 casing. Cap with 10  
sacks cement.

Cleaned and ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

TITLE

DATE

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: