

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLI
(Other instructions
verse side)E-
re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0174830-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Mona Federal

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Undesignated

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

17-T8S-R33E

12. COUNTY OR PARISH 13. STATE

Chaves

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. TA
OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

Atlantic Richfield Company

3. ADDRESS OF OPERATOR

P. O. Box 1710, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FSL & 1980' FWL (Unit letter K)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4413' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

Tobac Penn only

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

On 1/14/76 rigged up, fished rods, recovered rods to 6600'. Top of 5/8" rod fish @ 6600'. Installed BOP. WIH w/free pt, tagged top of fish @ 6632' WLM. Free pt indicated pipe free 0-6632'. POH w/free pt. WIH w/string shot to TOF @ 6632'. Backed off 2-3/8" OD EUE tbg @ 6617', pulled & recovered. WIH w/4 1/2" pkr on 2-3/8" OD EUE tbg, set pkr @ 6580'. Pmpd past fish w/3000# @ 1.5 BPM. Press up on 4 1/2" csg to 1500# OK. POH w/pkr & tbg. WIH w/4 1/2" cmt retr on 2-3/8" tbg. Set retr @ 6584'-RKB. Spotted cmt & displaced 100 sx Cl C cmt cont'g 4% gel, 8# salt & .5% Halad 22 below retr. MP 2400#. PU, spotted 10 sx cmt on top of retr. TOC @ 6494', RO 15 sx cmt. POH w/cmt tool & 2-3/8" tbg. Rem BOPs. Installed valve on wellhead. Temporarily abandoned 1/21/76. Final Report.

This approval of temporary FEB 1 1977
abandonment expires

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Dist. Drlg. Supv.

DATE 1/23/76

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED FOR RECORD
MAR 16 1976

*See Instructions on Reverse Side

GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

RECEIVED

MAR 23 1976

OIL CONSERVATION: COMM.
DOBBS, N. M.