

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name	
2. Name of Operator Cabot Corporation		8. Farm or Lease Name Signal State	
3. Address of Operator c/o Hobbs Pipe & Supply Co., Box 2010, Hobbs, N. M. 88240		9. Well No. 1	
4. Location of Well UNIT LETTER <u>A</u> <u>660'</u> FEET FROM THE <u>North</u> LINE AND <u>660'</u> FEET FROM THE <u>East</u> LINE, SECTION <u>29</u> TOWNSHIP <u>8-S</u> RANGE <u>33-E</u> NMPM.		10. Field and Pool, or Tract Tobac-Penn	
15. Elevation (Show whether DF, RT, GR, etc.) 4407' K.B.		12. County Chaves	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spotted a 25 sx cement plug from 9058'-9068'.
2. Spotted a 25 sx cement plug @ 4 $\frac{1}{2}$ casing stub @ 4350'.
3. Spotted a 25 sx cement plug @ 8-5/8 casing shoe @ 3650'.
4. Spotted a 25 sx cement plug @ 8-5/8 casing stub @ 1250'.
5. Spotted a 25 sx cement plug @ 13-3/8 casing shoe @ 370'.
6. Spotted a 10 sx cement plug @ surface.
7. Hole was loaded w/mud-laden fluids.
8. Well was plugged & abandoned on 4/26/72.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Agent DATE 5/8/72

APPROVED BY [Signature] TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAY 10 1972

OIL CONSERVATION COMM.
HOBBS, N. M.