

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

NEW MEXICO OIL CONSERVATION COMMISSION

HOBBS OFFICE O.C.C.
APR 25 11 17 AM '69

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

| | |
|---|------------------------------|
| Indicate Type of Lease | |
| State <input checked="" type="checkbox"/> | Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No. K-6795 | |

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| | | |
|---|--|---|
| 1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Plugged and abandoned | | 7. Unit Agreement Name None |
| 2. Name of Operator Roger C. Hanks | | 8. Farm or Lease Name Tidewater-State |
| 3. Address of Operator 606 Ball Tower West, Midland, Texas 79701 | | 9. Well No. 1 |
| 4. Location of Well UNIT LETTER H 1980 FEET FROM THE North LINE AND 660 FEET FROM THE East LINE, SECTION 31 TOWNSHIP 8S RANGE 33E NMPM. | | 10. Field and Pool, or Wildcat Tobac (Penn) |
| 15. Elevation (Show whether DF, RT, GR, etc.) | | 12. County Chaves |

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

| | | | |
|--|---|---|--|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input checked="" type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> | CASING TEST AND CEMENT JOB <input type="checkbox"/> | OTHER <input type="checkbox"/> |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3/13/69 Moved Hobbs Pipe & Supply rig and equipment on location and rigged up.

3/17
3/24/69 Well was plugged and abandoned by placing 25 sack cement plug over perforations at 9250'. Plugs of 25 sacks each were then placed at 4195' (stub of 4 1/2") and at 3657' (bottom of 8 5/8"). Plugs of 25 sacks each were placed at the stub of the 8 5/8" and the bottom of the 13 3/8". Surface plug-10 sacks. Space between all plugs filled with 10# drilling mud. Marked with permanent marker. Recovered 4214.23' of 4 1/2" OD csg. and 793.07' of 8 5/8" OD csg. Cleaned location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Roger C. Hanks TITLE **Owner** DATE **4-24-69**

APPROVED BY John W. Runyan TITLE **Manager** DATE **4-24-69**

CONDITIONS OF APPROVAL, IF ANY: