

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-9089	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Plugging oil well</u>		7. Unit Agreement Name ---
2. Name of Operator <u>Humble Oil & Refining Company</u>		8. Farm or Lease Name <u>New Mexico State BW</u>
3. Address of Operator <u>P. O. Box 2100, Hobbs, New Mexico</u>		9. Well No. <u>4</u>
4. Location of Well UNIT LETTER <u>J</u> <u>1988</u> FEET FROM THE <u>South</u> LINE AND <u>1997</u> FEET FROM THE <u>East</u> LINE, SECTION <u>16</u> TOWNSHIP <u>8-S</u> RANGE <u>33-E</u> NMPM.		10. Field and Pool, or Wildcat <u>Tobac Pennsylvanian</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>4398 D. F.</u>		12. County <u>Chaves</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugs set as follows:

Plug #1 from 9100 to 8900 with 20 sxs. cement.
Plug #2 from 6300 to 6200 with 20 sxs. cement.
PLUG #3 from 4946 to 4846 with 25 sxs. cement.
Plug #4 from 3660 to 3560 with 25 sxs. cement.
Plug #5 from 40 to surface with 10 sxs. cement.

Pulled 6280' of 4-1/2" casing shot at 6280'.
Mud laden fluid between plugs.
Installed dry hole marker per NMCCC requirement.

Location cleaned and levelled. Ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Dist. Adm. Supvr.</u>	DATE <u>June 25, 1965</u>
APPROVED BY <u>[Signature]</u>	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		