

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
06-6006

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name
2. Name of Operator Exxon Corporation	8. Farm or Lease Name Tobac State Oil Com
3. Address of Operator Box 1600, Midland, TX 79702	9. Well No. 1
4. Location of Well UNIT LETTER <u>D</u> , <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>21</u> TOWNSHIP <u>8-S</u> RANGE <u>33-E</u> NMPM.	10. Field and Pool, or Wildcat Tobac Penn
15. Elevation (Show whether DF, RT, GR, etc.) 3993	12. County <u>Lea</u> <u>Charles</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pulled production equipment.
2. Set CIBP at 4250' w/5sx cement on plug.
3. Cut 4 1/2" casing at 3600'. Could not pull, cut casing at 1450', pulled 1450' 4 1/2" casing.
4. Set 15 sx cement plug from 3426 - 3696'. Set 15 sx cement plug 1323 - 1508', set 40 sx plug from 220 - 425'. Set 10' cement plug at surface.
5. Install dry hole marker as required by Oil Conservation Commission.
6. Well Plugged and Abandoned 2-15-82.
7. C-103 will be forwarded when location has been cleaned and is leveled.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>S. H. Lowe</u>	TITLE <u>Sr. Administrator</u>	DATE <u>3/17/82</u>
APPROVED BY <u>Jack Griffin</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>JAN 05 1983</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

MAR 18 1982

CLERK
HOBBS OFFICE