	←		
NO. OF COPIES RECEIVED DISTRIBUTION SANTA FE			Form C-193 Supersedes Old C-102 and C-103 Effective 1-1-65
U.S.G.S. LAND OFFICE OPERATOR			5a. Indicate Type of Lease State Fee 5. State Oil & Gas Lease No
			E-9089
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)			
I. OIL GAS WELL	OTHER•	·	7. Unit Agreement Name
EXXONI CORPORATION			8. Farm or Lease Name
3. Address of Operator			JOBAC STATE OIL COM 'A'
P.O. BOX 1600, MIDL.	AND TEXAS 797	201	1
4. Location of well		T LINE AND 2130 FEET FR	10. Field and Pool, or Wildcat Tobac PENNSYL VANIAN
THE SOUTH LINE, SECTION_			
	15. Elevation (Show whether 4393		12. County CHAVES
Check Ap		lature of Notice, Report or C	Other Data NT REPORT OF:
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON	REMEDIAL WORK COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER CLEAR OUT, PE	ALTERING CASING PLUG AND ABANDONMENT
17. Describe Proposed or Completed Opero work) SEE RULE 1 (03,			
11-13-74 MOUE IN BA STUCK TEG. @ 7375, OVERSMOT & JARS, F PLD TBL & FISH, RA. SWEDCE, RAN 378": TBC & COLLAR JARS & & TBC & COLLAR JARS & & TBC & PLD 80 JTS PERFD 41/2" CSC 8 GO SÉT @ 8950, RUNCO FALS COREXIT 7652 CRUDE @ 5.8 BPM. 1	CUT PIPE ST @ 75 ISHED PIPE & JARI N 3½" SWEDCE & CO SWEDCE, CULLAR & SWEDCE, PUT ON O TBG. //- 18-74, P 93. 9002 W// JS, ACDZ PERFS W/ 9 15 CALS DOWE	SIS 2 NO CUT @ 73 RED PIPE THRU TION OLLARS. 11-15-74, F JARS FASHD SWED OVERSMOT, RAN JA LD TBC OUT OF H 1/F. 11-19-74, RA 3000 CALS 15%	CHT PLACE @ 7480, PLD TBL, COLLAR & 3% PLD TBL, COLLAR & 3% PLD TBL, COLLAR & 3% PLD COLLAR SWEDGE FOLE WESTER & PICE IN HOLE HC) CONTAINING 3 FED W/70 BBLS LEAS