

Hole Deviation Survey
Tom L. Ingram - No. 2 Garretson

350' - $1/4^{\circ}$	4880' - 1°
800' - $1/4^{\circ}$	5150' - 1°
1200' - $1/2^{\circ}$	5731' - $3/4^{\circ}$
1592' - $1/2^{\circ}$	5976' - $1/2^{\circ}$
1995' - $1/2^{\circ}$	6215' - 1°
2300' - $1-3/4^{\circ}$	6400' - $3/4^{\circ}$
2459' - $3/4^{\circ}$	6768' - $3/4^{\circ}$
2710' - 0°	7100' - $3/4^{\circ}$
2960' - 0°	7255' - $1-1/4^{\circ}$
3206' - 0°	7550' - $3/4^{\circ}$
3455' - $1/4^{\circ}$	7910' - $1/2^{\circ}$
3580' - $3/4^{\circ}$	8109' - $3/4^{\circ}$
3950' - $3/4^{\circ}$	8232' - $1/2^{\circ}$
4310' - $3/4^{\circ}$	8400' - 1°
4510' - $3/4^{\circ}$	8580' - 1°
4685' - $1-1/4^{\circ}$	8870' - $1-1/4^{\circ}$

State of New Mexico)
) SS.
County of Chaves)

I certify that this is a true and correct statement of the Hole Deviation for the
No. 2 Garretson, Section 25, T-8-S, R-32-E, Chaves County, New Mexico

By Tom L. Ingram
Title Owner

Sworn and subscribed to before me the undersigned authority on this 21st. day of
May, 1965.

James Hayes
Notary Public in and for Chaves
County, New Mexico

My Commission Expires:

March 4, 1969