

Hole Deviation Survey
Tom L. Ingram - No. 2 Garretson

350' - $1/4^{\circ}$	4880' - 1°
800' - $1/4^{\circ}$	5150' - 1°
1200' - $1/2^{\circ}$	5731' - $3/4^{\circ}$
1592' - $1/2^{\circ}$	5976' - $1/2^{\circ}$
1995' - $1/2^{\circ}$	6215' - 1°
2300' - $1-3/4^{\circ}$	6400' - $3/4^{\circ}$
2459' - $3/4^{\circ}$	6768' - $3/4^{\circ}$
2710' - 0°	7100' - $3/4^{\circ}$
2960' - 0°	7255' - $1-1/4^{\circ}$
3206' - 0°	7550' - $3/4^{\circ}$
3455' - $1/4^{\circ}$	7910' - $1/2^{\circ}$
3580' - $3/4^{\circ}$	8109' - $3/4^{\circ}$
3950' - $3/4^{\circ}$	8232' - $1/2^{\circ}$
4310' - $3/4^{\circ}$	8400' - 1°
4510' - $3/4^{\circ}$	8580' - 1°
4685' - $1-1/4^{\circ}$	8870' - $1-1/4^{\circ}$

State of New Mexico)
County of Chaves) SS

I certify that this is a true and correct statement of the Hole Deviation for the
No. 2 Garretson, Section 25, T-8-S, R-32-E, Chaves County, New Mexico

By Tom L. Ingram
Title Surveyor

Sworn and subscribed to before me the undersigned authority on this _____ day of
_____, 1965.

My Commission Expires:

March 4, 1969

Notary Public in and for Chaves
County, New Mexico

[Handwritten signature]