

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-005-10448
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	NM-1083

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name Haley Chaveroo San Andres Unit Sec. 3
2. Name of Operator Murphy Operating Corporation	8. Well No. 3
3. Address of Operator P. O. Drawer 2648, Roswell, New Mexico 88202-2648	9. Pool name or Wildcat Chaveroo San Andres
4. Well Location Unit Letter <u>C</u> : <u>410</u> Feet From The <u>North</u> Line and <u>3300</u> Feet From The <u>East</u> Line Section <u>3</u> Township <u>8 South</u> Range <u>33 East</u> NMPM Chaves County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

09-05-90 TOH with rods, pump and tubing. TIH with casing scrapper and clean out well to
to 4375'. TOH. TIH and perforate (1JSPF) @ 4312', 4342', 4360', 4370', 4373.5',
09-10-90 4376 TOH. TIH with packer and set @ 4130'. Acidize with 4000 gals 15% NeFe
(Pentol) 500# benzoic flake and 500# rock salt and 36 ball sealers. Good block
action, well balled of. Max rate 5 BPM, Max pressure 3000 psi, Avg. rate 4.5 BPM,
Avg. pressure 2000 psi, ISIP 1400#, 5" SIP 1300#, 10" SIP 1200#, 15" SIP 1150.
TOH with packer. TIH with tubing, pump and rods. Begin production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Lori Brown TITLE Production Supervisor DATE 9-27-90
TYPE OR PRINT NAME Lori Brown TELEPHONE NO. _____

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: