

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-4495
7. Unit Agreement Name
8. Farm or Lease Name NEW MEXICO "BX" STATE
9. Well No. 6
10. Field and Pool, or Wildcat CHAUVEROD SAN ANDRES
12. County CHAVES

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>
2. Name of Operator EXXON CORPORATION
3. Address of Operator P.O. Box 1600 MIDLAND, TEXAS 79701
4. Location of Well UNIT LETTER A 660 FEET FROM THE N LINE AND 660 FEET FROM THE E LINE, SECTION 16 TOWNSHIP 8-S RANGE 33-E NMPM.
15. Elevation. (Show whether DF, RT, GR, etc.) 4406 DF

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PULL RODS & PUMP. CIRCULATE HOLE WITH MUD CONSISTING OF 25 SX
GEL/100 BBLs. BRINE. PULL & LAY DOWN TBG. SET A CIBP AT 4220'
AND DUMP 30' (3 SX) CEMENT ON TOP. DETERMINE FREE POINT AND
CUT OFF 4 1/2" CSG AT ABOUT 3200'. SPOT THE FOLLOWING 100'
CLASS H CEMENT PLUGS THROUGH THE 4 1/2" CSG AS IT IS PULLED.
PUMP PLUGS DOWN WITH MUD.

75 60 SXs 1400-1500 BETWEEN RUSTLER & SANTA ROSA
85 70 SXs 150-250 ACROSS 8 5/8" CSG SEAT AND BELOW OCHALLALA.
10 SXs 0-10 SURFACE

SET WELL MARKER & CLEAN UP LOCATION. CALL NMOC REPRESENTATIVE
TO INSPECT

75 SXs @ Base 52 ft
75 SXs @ 4 1/2 stub

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Joe D. Farney TITLE UNIT HEAD DATE 11-12-74
APPROVED BY Joe D. Farney TITLE Dist. I, Supv. DATE _____
CONDITIONS OF APPROVAL, IF ANY: