

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

3 NMOCD (Hobbs)

1 File

1 Pennant Pet.

Form C-103

Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.
30-005-10464
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. K-527
7. Lease Name or Unit Agreement Name KM Chaveroo SA Unit
8. Well No. 33
9. Pool name or Wildcat *Chaveroo (San Andres)

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☐ GAS WELL ☐ OTHER ☐ Water Injection Well\*

2. Name of Operator  
Dugan Production Corp.

3. Address of Operator  
P.O. Box 420, Farmington, NM 87499

4. Well Location  
Unit Letter H : 1980 Feet From The North Line and 660 Feet From The East Line  
Section 2 Township 8S Range 33E NMPM Chaves County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4378' RKB

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: TA ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is requested that this water injection well be temporarily abandoned effective March 23, 1995.

Well No. 33 was pressure tested to 300 psig for 15 minutes in compliance with OCD guidelines and witnessed by Mr. Lyle Turnacliffe, NMOCD. A copy of the pressure chart is on the reverse side of this sundry.

The well is equipped with plastic coated tubing and tension packer set at 4137 feet.

This Approval of Temporary  
Abandonment Expires

5-1-2000

I hereby certify that the information above is true and complete to the best of my knowledge and belief.


SIGNATURE Jim L. Jacobs TITLE Vice-President DATE 5/5/95  
TYPE OR PRINT NAME Jim L. Jacobs TELEPHONE NO. 505-325-1821

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE MAY 11 1995

CONDITIONS OF APPROVAL, IF ANY:



RECEIVED

196