

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-005-10467
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	NM-1083

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name Haley Chaveroo San Andres Sec. 3
2. Name of Operator Murphy Operating Corporation	8. Well No. 8
3. Address of Operator P. O. Drawer 2648, Roswell, New Mexico 88202-2648	9. Pool name or Wildcat Chaveroo San Andres
4. Well Location Unit Letter H : 1980 Feet From The North Line and 660 Feet From The East Line Section 3 Township 8 South Range 33 East NMPM Chaves County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Convert to Injection Well R-8760 ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-16-90 Rig up pulling unit. Pick up bailer. SLM in hole with 2 3/8" J-55
4.7# coated tubing. Ran 50 Jts SDFN.

5-17-90 Finish picking up tubing. Top of fill @ 3335' bail out to 4408'.
Tool plugged, TOH & lay bailer down. Rig up logging truck & TIH
with perf guns & perforate as follows (1JSPF) @ 4356', 4363', 4369'
& 4373'. TOH & rig down logging truck.
TIH as follows:

1 Haliburton R-4 Packer	3.45
131 Jts. 2 3/8" J-55 4.7# coated tubing	4106.29
KBM correction	11.50
Pull 18 point set packer @	4121.24

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Lori Brown TITLE Production Supervisor DATE 6/11/90
TYPE OR PRINT NAME Lori Brown TELEPHONE NO. 505-623-7210

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

JUN 21 1990

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUN 20 1990

OCD
HOBBS OFFICE

