[
NO. OF COPIES RECEIVED	· •	Form C-103
DISTRIBUTION	- No. 2	Supersedes Old C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE	SEP 12 9 25 M1'66	
U.S.G.S.	OEL 17 0 50 191 00	5a. Indicate Type of Lease
LAND OFFICE		State X Fee.
OPERATOR		5. State Oil & Gas Lease No.
		OG 1195
SUNDRY	NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOUSE **APPLICATION	NOTICES AND REPORTS ON WELLS DSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. N FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1.		7. Unit Agreement Name
OIL GAS WELL	OTHER-	
2. Name of Operator		8. Farm or Lease Name
Atlantic Richfield Company		State "BF"
3. Address of Operator		9. Well No.
P. O. Box 1978, Roswell, New Mexico		5
4. Location of Well		10. Field and Pool, or Wildcat
2.	20 15	
UNIT LETTER	30 FEET FROM THE NORTH LINE AND 990 FEE' F	ROM CHAVELOO-SAN ANGLES
	2 22 7	
THE West LINE, SECTION	3 TOWNSHIP 8-S RANGE 33-E NM	1PM.
······································	The property of the property o	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	4415' DF	Chaves \\\\\\\
Check Ap	ppropriate Box To Indicate Nature of Notice, Report or	Other Data
NOTICE OF INT		ENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	TEG AND ABARDONMENT
		
OTHER	OTHER Completion	X _
OTHER		
Formation Density, surveys. Ran 138 collar & float she l:1 Incor-Diamix Top of cement @ 324-1/2" casing to wore 3/8" OD jet 15% HCl acid. Swatainer @ 4409 & se 4000#. WOC 36 how 4225, 4319, 4323, gal. lease crude of load oil. On 8 4366-71 & 4385-90	le to 4500' T.D. (RKB). On 7/15/66 ran Laterolog, Microlaterolog w/Caliper jts of 4-1/2" OD 8R 10.5# J-55 ST&C De = 4485.83'. Set at 4499' RKB. Cet 5/10 of 1% D-30. Plug down at 4:30 211' by temperature survey. After 42 1500# for 30 min. Held OK. Perforat shot @ 4429, 4436, 4445 & 4450. Tre abbed dry w/slight show of gas & oil. Queezed above perfs w/41 sx cement. Ars. Perforated San Andres w/one 3/8 4335, 4361 & 4372'. Treated w/3000 at 30,000# 20/40 sand on 7/23/66. Fai 3/13/66 perforated San Andres 4319-24 w/2 JSPF. Treated w/1000 gal. acid,	& Sidewall Neutron casing w/float mented w/300 sx P.M. 7/16/66. hours WOC tested ed lower San Andres ated w/1500 gal. Set cement re- Max. & final press= " OD jet shot @ gal. 15% HCl, 20,000 led to recover all, 4340-45, 4352-57,
	0/40 sand. Now pumping load.	
SIGNED	THILE Dist. Drlg. Superviso	r_ DATE 9-9-66
APPROVED BY	TITLE	DATE
ACCRUYED BY		UA15

CONDITIONS OF APPROVAL, IF ANY: