

DISTRICT I
P.O. Box 1983, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL AP. NO.	30-005-10490
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	NM-1083

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name Haley Chaveroo San Andres Sec. 3
2. Name of Operator Murphy Operating Corporation	8. Well No. 6
3. Address of Operator P. O. Drawer 2648, Roswell, New Mexico 88202-2648	9. Pool name or Wildcat Chaveroo San Andres
4. Well Location Unit Letter <u>F</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>3</u> Township <u>8 South</u> Range <u>33 East</u> NMPM <u>Chaves</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Convert to Injection Well <u>R-8760</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-14-90 Rig up mast & wireline truck. TIH with perf guns perforate as follows (1JSPF) @ 4300', 4310', 4316', 4384', 4391' & 4393'. TOH with perf guns. Rig down mast & wireline truck.

5-15-90 Rig up pulling unit & SDFN.

5-16-90 Pick up packer SLM in hole as follows:

1 Haliburton R-4 Packer	3.45
131 Jts 2 3/8" 4.7# coated tubing	4118.58
KBM correction	11.50
Pull 15 points set packer @	4133.53

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Lory Brown TITLE Production Supervisor DATE 6/11/90
TYPE OR PRINT NAME Lory Brown TELEPHONE NO. 505-623-7210

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ DATE JUN 21 1990

CONDITIONS OF APPROVAL, IF ANY:

