

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRI-STATE\*  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.NMOC - AREA  
NMOC - ROADS  
BLM - SANTA FE

## SUMMARY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Dry Hole		5. LEASE DESIGNATION AND SERIAL NO. NM-027395
2. NAME OF OPERATOR Pubco Petroleum Corporation		6. IF INDIAN, ALLOTTED OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 869, Albuquerque, New Mexico 87103		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1650' fSL, 1980' fEL, Sec. 33-T8S-R31E		8. FARM OR LEASE NAME Pubco Federal
14. PERMIT NO.		9. WELL NO. #14
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4268 DF		10. FIELD AND POOL, OR WILDCAT Wildcat
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 33-T8S-R31E
		12. COUNTY OR PARISH Chaves
		13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Perforated San Andres 3794-3809 and acidized with 2000 gal. Swabbed at rate of 350 bbls. fluid per day, 1% oil, 99% wtr. Propose to plug and abandon as follows:

1. Cut off 4-1/2" csg. as indicated by free point and pull;
2. Set cement plugs with tubing as follows:
  - a. 3750 - 3850 ft.
  - b. 100 ft. across 4-1/2" cutoff
  - c. 1850 - 1950 ft. (Yates)
  - d. 300 - 350 ft., base surface csg.
3. Set 10 ft. cement plug at surface with 4 in. pipe dry hole marker.

Work will begin 10/6/66. Verbal approval obtained from J. W. Sutherland on 10/5/66.

RECEIVED  
OCT - 6 1966  
U. S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Charles E. Ramsey, Jr.

TITLE Area Production Manager

DATE October 5, 1966

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

TITLE

DATE

OCT 6 1966

J. W. SUTHERLAND  
DISTRICT ENGINEER

\*See Instructions on Reverse Side