	~				
NO. OF COPIES RECEIVED	7				
DISTRIBUTION			Form C-103 Supersedes Old		
SANTA FE	Monac Con de G.C.C.		C-102 and C-	103	
FILE	NEW MEXICO OIL CONSERVATION COMMISSION		Effective 1-1-	65	
	⊣ Aug	9 6 ai AM '68	Co. Indiana Trans		
U.S.G.S.	-		5a. Indicate Type		
LAND OFFICE	-		State	Fee 🔀	
OPERATOR	ــــــــــــــــــــــــــــــــــــــ		5. State Oil & Ga	is Lease No.	
SLINDS	OV NOTICES AND DEPORTS ON	WELLS	mmm	mmmm	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT —" (FOR WICH PROPOSALS.)					
1 DRV HOLE TO BE			7. Unit Agreement Name		
OIL GAS WELL	OTHER USED AS S	// N			
2. Name of Operator				Name	
PAN AMERICAN PETROLEUM CORPORATION				CATO SALT WATER	
3. Address of Operator				DISPOSAL SYSTEM	
BOX 68, HOBBS, N. M. 88240				5,	
4. Location of Well			10. Field and Pool, or Wildcat		
M 660 Sauth 660			1	or wrided	
UNIT LETTER M., 660 FEET FROM THE SOUTH LINE AND 660 FEET FROM				······	
THE WEST LINE, SECTION 3 TOWNSHIP 8-S RANGE 30-E NMPM.					
THE WEST LINE, SECTI	ON TOWNSHIPO"	S RANGE SO-C NMPM	<i>.\\\\\\</i>		
	15. Elevation (Show whether	DE DT CD	<u> </u>	4444444	
	13. Elevation (show whether	Dr, KI, GR, etc.)	12. County		
İmmi	40 (6	R. U. D.	<u> CHRUES</u>	VIIIIII	
Check	Appropriate Box To Indicate N	Nature of Notice, Report or Ot	her Data		
	NTENTION TO:		T REPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERI	ING CASING	
TEMPORARILY ABANDON	_	COMMENCE DRILLING OPNS.		NO ABANDONMENT	
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	F.00 X	un vedunoument	
CONVERSION O	F WELL -	OTHER			
OTHER PREPARATION	V OF WELL FOR X				
SW DISPOSA	<u>۸</u> ،				
17. Describe Proposed or Completed O work) SEE RULE 1103.	perations (Clearly state all pertinent det	ails, and give pertinent dates, including	estimated date of s	tarting any proposed	
•	~ -				
WELL NAME FO	RNIERLY- SELLI	ERS NO.1			
TO DOE DAD NO	- WELL FOR INJ	ECTION ADDITION	AL MARK	DEONIE	
	.				
PROPOSE: S. POT	25 04 cement plus	g from PBD 3318	TO ADPX	3/00.	
(PERFS 3252.336	3). 20 P4 plug	1900-1350, Cut	4/2" Casa	ing	
@ 1258 + Reciprocate pipe and establish circulation. Cement					
41/2" W/200 sx Incor 12% gil salt sul. + 225 st Incor next,					
salt sal. circulate on the back into surface. NOC.					
Perforate Rustler formation 1005-10035 W/25 PF. acidize					
Perforace occur	uce formation	1005-10035 4/25	PF. acid	ze	
W/300 and, m	CA. Swab test.	aptain water	. Almal	101	
	is to be		, A	· ·	
Kun injeden	ty tests. In	ubmit result	5 100		
requeatory	Trais.				
The state of	000000				
75 3 45 - 44.5	0 - 2 don'				
	CSA 3402				
18. I hereby certify that the information	a shove is true and complete to the best of	of my knowledge and helief.			
7	Anr	A cimenia mesioni m	AUG 9	1968.	
SIGNED	TITLE AKE	A SUPERINTENDENT	DATE		
0+ 2- NMOCC-11	//				
1-NSW John	W Kenne	• .	* · ·		
APPROVED BY	. Manyan TITLE 11		DATE		
CONDITIONS SPAR ROVAL, IF ANY					
1-RRy					
,					