

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

3 NMOC (Hobbs) Form C-103
1 File Revised 1-1-89
1 Pennant Pet.

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
30-005-10524
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. OG-1062
7. Lease Name or Unit Agreement Name KM Chaveroo SA Unit
8. Well No. 110
9. Pool name or Wildcat *Chaveroo (San Andres)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4375' RKB

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> Water OTHER Injection Well*
2. Name of Operator Dugan Production Corp.
3. Address of Operator P.O. Box 420, Farmington, NM 87499
4. Well Location Unit Letter N : 990 Feet From The South Line and 1980 Feet From The West Line Section 2 Township 8S Range 33E NMPM Chaves County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4375' RKB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: TA ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is requested that this water injection well be temporarily abandoned effective March 23, 1995.

Well No. 110 was pressure tested to 490 psig declining to 480 psig in 15 minutes in compliance with OCD guidelines and witnessed by Mr. Lyle Turnacliiff, NMOC. A copy of the pressure chart is on the reverse side of this sundry.

The well is equipped with plastic coated tubing and tension packer set at 4146 feet.

This Approval of Temporary
Abandonment Expires 5-1-2000

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jim L. Jacobs TITLE Vice-President DATE 5/5/95
TYPE OR PRINT NAME Jim L. Jacobs TELEPHONE NO. 505-325-1821

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

MAY 11 1995

